



IRM services LLC (984) 293-4948 irmservicesllc.org

Home Inspection Report Sample Report

Inspected By: Brandon Stewart

Prepared For: First Name Last Name Inspected On Tue, Feb 13, 2024 at 3:00 PM

Table of Contents

General	
Site	
Exterior	7
Garage	
Roofing	
Structure	
Electrical	
HVAC	
Plumbing	
Kitchen	
Laundry	
Interior	25
Report Summary	

Thank you for the opportunity to conduct a home inspection of this property. We understand that the function of this report is to assist you in understanding the condition of the property to assist in making an informed purchase decision.

The report contains a review of components in the following basic categories: site, exterior, roofing, structure, electrical, HVAC, plumbing, and interior. Additional categories may or may not be included

The report is designed to be easy to read and comprehend however it is important to read the entire report to obtain a full understanding of the scope, limitations and exclusions of the inspection.

In addition to the checklist items of the report there are typically several report comments which are meant to help you further understand certain conditions observed.

These are easy to find while reading the report. There is a colored bar along the left margin and each comment is labeled with a type of comment.

Comments with the highest severity are also displayed on the report summary. Please read all the comments.

DEFINITION OF CONDITION TERMS

Satisfactory: At the time of inspection the component is functional without observed signs of a substantial defect.

Marginal: At the time of inspection the component is functioning but is estimated to be nearing end of useful life. Operational maintenance recommended. Replacement anticipated.

Repair or Replace: At the time of inspection the component does not function as intended or presents a Safety Hazard. Repair or replacement is recommended.

Further Evaluation: The component requires further technical or invasive evaluation by qualified professional tradesman or service technician to determine the nature of any potential defect, the corrective action and any associated cost.

General information about the property inspected and the conditions that existed when the inspection was performed.

Overview Photos Of Property



Approximate Age 10 year old Age Based On Listing **Bedrooms/Baths** 4/3 **Door Faces** Southeast Furnished No Occupied No Weather Sunny Temperature 63°F

Soil Condition

Damp

Utilities On During Inspection

Electric Service, Gas Service, Water Service

People Present

Client, Buyer's Agent

General Comments

Comment 1 Information

This report is a sample and not a real report. This is our template and software system we use but photos are a combo of stock and pictures taken from multiple inspections to protect clients.

Aged homes may contain lead paint, lead pipes or water supplies, asbestos, containing materials, insufficient, insulation, leaking, ductwork, obsolete, electrical systems, and/or other defects that are concealed. Performing technical test to confirm the chemical composition of substances is beyond the scope of a general inspection. Not all defects are able to be observed during the course of a home inspection and may be identified during future construction upgrades, and or through specialized inspections by qualified specialist.

The condition of the vegetation, grading, surface drainage and retaining walls that are likely to adversely affect the building is inspected visually as well as adjacent walkways, patios and driveways.

Site Grading

Sloped Away From Structure Condition: Satisfactory

Vegetation

Generally Maintained Condition: Satisfactory

Driveway

Concrete Condition: Satisfactory

Walkways

Concrete Condition: Satisfactory

Steps/Stoops

Concrete Condition: Satisfactory

Patios/Decks

Wood Condition: Satisfactory The visible condition of exterior coverings, trim and entrances are inspected with respect to their effect on the condition of the building.

Exterior Covering

Vinyl Siding Condition: Satisfactory

Exterior Trim Material

Vinyl Condition: Satisfactory

Windows

Aluminum Condition: Satisfactory

Entry Doors

Steel Condition: Satisfactory

Garage Type Attached Condition: Satisfactory

Overview Photos Of Garage









Door Opener Belt Drive Condition: Satisfactory

Opener Safety Feature Light Beam, Force Sensitive

Condition: Satisfactory

Garage Comments

Comment 2 Monitor Condition

Monitoring is required if a problem may present itself later.

Roofing

The visible condition of the roof covering, flashings, skylights, chimneys and roof penetrations are inspected. The purpose of the inspection is to determine general condition, NOT to determine life expectancy.

Inspection Method

Walked Roof/Arms Length

Roof Covering

Dimensional Condition: Satisfactory

Photo Of Each Roofing Type



Approximate Roof Age Original

Ventilation Present

Roof, Soffit, Gable Ends Condition: Satisfactory

Vent Stacks

Metal, Plastic Condition: Satisfactory

Flashings

Metal Condition: Satisfactory

Soffit and Fascia Aluminum, Vinyl Condition: Satisfactory

Gutters & Downspouts

Metal Condition: Satisfactory

Roofing Comments

Comment 3 Repair or Replacement Needed

Defects are written when function isn't working properly, broken or installation is wrong.

These statements will have the defect with photos, description, implication or why it's wrong and direction.

Structure

The visible condition of the structural components is inspected. The determination of adequacy of structural components is beyond the scope of a home inspection.

Foundation Types

Slab on Grade

Foundation Material

Poured Concrete Condition: Satisfactory

Floor Structure

Concrete Slab Condition: Satisfactory

Subflooring

Oriented Strand Board Condition: Satisfactory

Wall Structure

Wood Frame Condition: Satisfactory

Attic

Attic Entry

Garage

Overview Photos Of Attic





Roof Framing Type Wood Trusses Condition: Satisfactory

Roof Deck Material

Oriented Strand Board Condition: Satisfactory

Vent Risers

Metal Condition: Satisfactory

Insulation

Blown In Fiberglass Condition: Satisfactory

Electrical

The inspector can not inspect hidden wiring or verify if the number of outlets is per the National Electric Code. A representative number of outlets, switches and fixtures are tested for operation.

Type of Service

Underground

Main Disconnect Location

Service Panel

Service Panel Location

Exterior

Photo of Panel





Service Panel Manufacturer Condition: Satisfactory

Service Line Material

Aluminum Condition: Satisfactory

Service Voltage

240 volts

Electrical Cont.

Service Amperage

200 amps

Service Panel Ground

Ground Rod

Branch Circuit Wiring

Non-Metallic Shielded Copper Condition: Satisfactory

Overcurrent Protection

Breakers Condition: Satisfactory

GFCI/AFCI Breakers

Yes Condition: Satisfactory

Smoke Detectors

Hard Wired Condition: Satisfactory

Electrical Comments

Comment 4 Safety Concern

Safety concerns are defects in which harm or injury may happen if not repaired.

Sub Panel

Location

Garage

Photo of Subpanel





Service Line Material

Aluminum

Overcurrent Protection

Breakers

Branch Circuit Wiring

Non-Metallic Shielded Copper Condition: Satisfactory

GFCI/AFCI Breakers

Yes Condition: Satisfactory

HVAC System Type

Central Split System

Thermostat

Digital Condition: Satisfactory

Photo of Thermostat



Thermostat Location

Hallway

Heating

The heating system is inspected visually and operated by normal controls to determine general condition NOT life expectancy. The capacity or adequacy of the heating system is beyond the scope of a home inspection. A licensed HVAC contractor should be consulted if in question.


Location

Attic

Type of Equipment

Forced Air Condition: Satisfactory

Photo of Furnace Operating



Manufacturer

Lennox

Heating Fuel

Gas Condition: Satisfactory

Approximate Age

10

Filter Type

Washable, Disposable Condition: Satisfactory

Type of Distribution

Flexible Ducting Condition: Satisfactory

Furnaces over 10 years old should be checked, cleaned and serviced yearly by a licensed contractor.

Cooling

The cooling system is inspected by operation of the equipment by normal controls to determine general condition NOT life expectancy. The capacity or adequacy of cooling system is beyond the scope of a home inspection. A licensed HVAC contractor should be consulted if in question.

Energy Source

Electric

Type of Equipment

Split System Condition: Satisfactory

Photo of Unit Operating



Condenser Make

Lennox

Condenser Approximate Age

10

Condesate Drainage

To Exterior Condition: Satisfactory

Air conditioners over 10 years old and heat pumps over 5 years old should be checked, cleaned and serviced yearly by a licensed contractor.

Plumbing

The plumbing system is inspected visually and by operating a representative number of fixtures and drains. Private water and waste systems are beyond the scope of a home inspection.

Water Service

Public

Supply Pipe Material

PEX Condition: Satisfactory

Location of Main Water Shutoff

Interior

Photo of Main Water Valve



Sewer System

Public

Waste Pipe Material PVC

Condition: Satisfactory

Location of Fuel Shutoff

At Meter

Water Heater

Photo of Water Heater



Manufacturer

Rinnai

Fuel

Natural Gas

Capacity

Tankless

Approximate Age

3

Temp & Pressure Relief Valve

Present With Blow Off Leg

Condition: Satisfactory

Fuel Disconnect

In Same Room

Overview Photo of Kitchen



Cabinets

Condition: Satisfactory

Countertops

Condition: Satisfactory

Sink

Condition: Satisfactory

Kitchen Comments

Comment 5 Information

Info is added on home components, function and testing.

Appliances

This is a cursory check only of the specified appliances. The accuracy or operation of timers, temperature or power level controls is beyond the scope of this inspection.

Range

Condition: Satisfactory

Range Hood Condition: Satisfactory

Dishwasher Condition: Satisfactory

Microwave Condition: Satisfactory

Sample Report

Disposal

Condition: Satisfactory

Laundry

Built In Cabinets

Yes Condition: Satisfactory

Laundry Sink

Yes Condition: Satisfactory

Dryer Venting

To Exterior Condition: Satisfactory

GFCI Protection

Yes Condition: Satisfactory

Laundry Hook Ups

Yes Condition: Satisfactory

Overview Photos of Laundry



Interior

The interior inspection is limited to readily accessible areas that are not concealed by furnishings or stored items. A representative number of windows and doors.

Fireplace

Manufactured Condition: Satisfactory

Overview Photos of Interior



This report summary is not the entire report. The complete report may include additional information of interest or concern to you. It is strongly recommended that you promptly read the complete report. For information regarding the negotiability of any item in this report under the real estate purchase contract, contact your real estate agent or an attorney.

Safety Concern

Electrical

Safety concerns are defects in which harm or injury may happen if not repaired.

Repair or Replacement Needed

Roofing

Defects are written when function isn't working properly, broken or installation is wrong.

These statements will have the defect with photos, description, implication or why it's wrong and direction.